

Features

- ◇ 2 position 2 port reversing valve (normally open) with G1/8 and G1/4 air entry ports returns the air signal through the vacuum switch to realize the air supply opening and closing and energy saving.
- ◇ The small valve can control a large flow of compressed air.



How to order

ZVAA - G1F

① ②

① Series

② Connection thread

ZVAA


G1F - G1/8 Female thread

G2F - G1/4 Female thread

Technical parameters

Air supply pressure (bar)	Output function	Ambient temperature (°C)	Material
3.5-7	NO(Normally open)	0-60°C	Aluminum alloy

Symbol



Dimensions (mm)

